

FITNESS CERTIFICATE

To be filled by the Inspecting Officer (Asst.Engineer)

1. Name of the Officer Sunilkumar MB.
2. Name of the Institution Crescent public School
3. Location Cherthala
4. Classification of Building 1. RCC Rect building (GF+1)
2x6200x870x3.20 (GF+FF)
5. Period for which the certificate is issued 2024-25
6. Nature of defects, if any
a) Foundation and basement
b) Superstructure
c) Doors and Windows
d) Woodwork wrought and put up
e) Roof
f) Flooring
g) Miscellaneous (Cracks, etc.)
7. Any major defects noticed which will render the building unsafe in any manner
8. Whether maintenance work has been done properly
9. Whether the structure is sound or not

Nil

Nil

No

Sound under normal weather and wind conditions of Kerala.

Note: 1. The stability of the structures should be examined also with reference to location, altitude, intensity of wind, exposure of flood etc. 2. Any additional observations if deemed necessary for the certificate may be furnished separately with this certificate.

(The toilet on the east side of the school is not usable for students)

CERTIFICATE

Certified that the building was inspected by me on 27/5/2024 and

Found to be fit/unfit for the period 2024-25 for the

Reasons stated above.

Place: Mannancherry

Date: 27/5/24



MB
ASSISTANT ENGINEER
LSGD (LID & EW) SECTION
MANNANCHERRY GRAMA PANCHAYATH